

FALLS RISK REGISTER

TASK	CAUSE OF RISK	RISK LEVEL	CURRENT CONTROLS	FURTHER ACTIONS	RESPONSIBLE PERSONS	DUE DATE	MANAGEMENT SIGN OFF WHEN COMPLETE
Roofing Activities	Falls from heights above 2m	<input type="checkbox"/> Acute <input checked="" type="checkbox"/> High <input type="checkbox"/> Moderate <input type="checkbox"/> Low	Training, Edge Protection, Scaffold, Safety Harness, Safe Work Procedures	Ensure training of all new workers and refresher training for workers as per Code of Practice recommendations	Vertec Roofing Supervisor	N/A	<i>Trent Simpson</i>
Roofing Activities	Falling Objects	<input type="checkbox"/> Acute <input checked="" type="checkbox"/> High <input type="checkbox"/> Moderate <input type="checkbox"/> Low	Mesh on scaffold, exclusion zones below, hard hats required, Safe Work procedures	Ensure training of all new workers and refresher training for workers as per Code of Practice recommendations	Vertec Roofing Supervisor	N/A	<i>Trent Simpson</i>
Movement on Construction Site	Mobile Plant	<input type="checkbox"/> Acute <input checked="" type="checkbox"/> High <input type="checkbox"/> Moderate <input type="checkbox"/> Low	Hi Vis Clothing, Follow TMP, trained plant operators, site induction	Ensure induction of workers onto site. Follow Site Rules. Workers hold White Cards	Vertec Roofing Supervisor	N/A	<i>Trent Simpson</i>